



**Photograph 1: Emergency Responder spraying wax on wreckage to sequester carbon fibers. This activity is described in the Hazardous Materials Incident Report present in Appendix A.**



**Photograph 2: Hydrocarbon absorbing boom in storm drain down hill from the crash site.**



**Photograph 3: Property along Huggins Avenue near crash site. Photograph shows amount of debris that accumulated in front yards in the vicinity of crash site.**



**Photograph 4: Air monitoring equipment during clean up activities.**