

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number CA9170024740	2. Page 1 of 1	3. Emergency Response Phone (800) 326-1011	4. Manifest Tracking Number 002043906 FLE			
5. Generator's Name and Mailing Address Commanding Officer (Environmental Mgmt) Box 452001 MCAS Miramar Bldg 6022 San Diego, CA 92145-2001 858-577-1107/6533				Generator's Site Address (if different than mailing address) MCAS Miramar 45249 Miramar Way San Diego, CA 92145				
6. Transporter 1 Company Name General Environmental Management, Inc.					U.S. EPA ID Number CAD983649880			
7. Transporter 2 Company Name					U.S. EPA ID Number			
8. Designated Facility Name and Site Address U.S. Ecology Corp. Highway 95 - 12 miles south of Beatty Beatty, NV 89003 800 239 3943 Facility's Phone:					U.S. EPA ID Number NVT330010000			
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
		No.	Type					
	1. Non-RCRA hazardous waste solid (Soil Contaminated with Fuels)	001	CM	00020	Y	181	352	223
	2.							
	3.							
	4.							
14. Special Handling Instructions and Additional Information 1x20 CY Roll Off 9807, HT85 In# 163 TW. 3390 wt. 163# Copy Manifest and CD to: 3191 Temple Ave #250 4406 CATREL, INDV. CTY. SP44000600009 001584 MCAS Miramar, Romona, CA 91768								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. COE DAN IRO CHARLES 2-04-09 I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offero's Printed/Typed Name ITAL CORONA				Signature <i>[Signature]</i>		Month Day Year 02/04/09		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:								
17. Transporter Acknowledgment of Receipt of Materials								
Transporter 1 Printed/Typed Name OSCAR LIVERA				Signature <i>[Signature]</i>		Month Day Year 02/04/09		
Transporter 2 Printed/Typed Name				Signature		Month Day Year		
18. Discrepancy								
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
18b. Alternate Facility (or Generator) U.S. EPA ID Number								
18c. Signature of Alternate Facility (or Generator) Month Day Year								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
2.		3.		4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name				Signature		Month Day Year		

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number CA9170024740	2. Page 1 of 1	3. Emergency Response Phone (800) 326-1011	4. Manifest Tracking Number 002043905 FLE			
5. Generator's Name and Mailing Address Shipping Officer (Environmental Mgmt) Box 452001 MCAS Miramar Bldg 6022 San Diego, CA 92145-2001 Generator's Phone: 858-577-1107/6533				Generator's Site Address (if different than mailing address) MCAS Miramar 45249 Miramar Way San Diego, CA 92145				
6. Transporter 1 Company Name General Environmental Management, Inc.					U.S. EPA ID Number CAD983649880			
7. Transporter 2 Company Name					U.S. EPA ID Number			
8. Designated Facility Name and Site Address U.S. Ecology Corp. Highway 95 - 12 miles south of Beatty Beatty, NV 89003 Facility's Phone: 800 239 3943					U.S. EPA ID Number NVE330010000			
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
		No.	Type					
	1. Non-RCRA hazardous waste solid (Soil Contaminated with Fuels)	001	CM	00020	Y	161	35Z	223
	2.							
	3.							
	4.							
14. Special Handling Instructions and Additional Information 1x20 CY Roll Off 9807, HT85 # 162 TW. 3430 wt. 15630 Copy Manifest and CD to: 3191 Temple Ave #250 4406 CATHEC, UNIV. CTY. SP44000600009 DO#584 MCAS Miramar Pomona, CA 91768								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. CORRAMIR CHARLES 2-04-09 I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offereor's Printed/Typed Name PAUL CORONA					Signature 		Month Day Year 02/04/09	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:								
17. Transporter Acknowledgment of Receipt of Materials								
Transporter 1 Printed/Typed Name JOSE T MASCAR				Signature 		Month Day Year 02/04/09		
Transporter 2 Printed/Typed Name				Signature		Month Day Year		
18. Discrepancy								
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
Manifest Reference Number:								
18b. Alternate Facility (or Generator) U.S. EPA ID Number								
Facility's Phone:								
18c. Signature of Alternate Facility (or Generator)						Month Day Year		
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
2.		3.		4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name				Signature		Month Day Year		