



Photograph 1: View to the south of the limited excavation at the northeast corner of 4406 Cather Avenue. Excavation conducted on February 4, 2009.



Photograph 2: View to the southwest of the limited excavation at the northeast corner of 4406 Cather Avenue.



Photograph 3: Monitoring for organic vapor in soil using a photo ionization detector.



Photograph 4: View to the south of limited soil excavation.



Photograph 5: Filling in excavation



Photograph 6: Complete view of excavation area



Photograph 7: View to the west toward Cather Avenue of the temporary storm water diversion channel along the northern extent of 4406 Cather Avenue.